

FIG.1




FIG.2(a)

FIG.2(b)




FIG.3(a)

FIG.3(b)




FIG.4(a)

FIG.4(b)




FIG.5(a)




FIG.5(b)




FIG.6(a)




FIG.6(b)




FIG. 7(a)




FIG. 7(b)




FIG. 7(c)




FIG. 8(a)




FIG. 8(b)




FIG. 8(c)




FIG.9(a)




FIG.9(b)




FIG.10




FIG.11




FIG.12(a)





FIG.12(b)










FIG.14





FIG.15



Example of Single Lens

FIG.16




FIG.17




FIG.18(b)




FIG.18(a)




FIG.18(d)




FIG.18(c)




FIG.18(f)




FIG.18(e)




FIG.19(b)




FIG.19(a)




FIG.19(d)




FIG.19(c)




FIG.20(b)

Transfer of functional surface by heating and pressure application




FIG.20(a)

Sliding fit formed by heating and deformation




FIG.21(b)




FIG.21(a)




FIG. 22(b)




FIG. 22(a)




FIG.23






FIG. 24(b)




FIG. 24(a)




FIG. 24(c)




FIG.25(b)




FIG.25(a)




FIG.25(d)





FIG.25(c)



Holding member for a low degree of straightness  
(sheet metal formed by stamping)

FIG. 26(b)




FIG.27(b)




FIG.27(a)

